MARYLAND INVENTORY OF HISTORIC BRIDGES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION/MARYLAND HISTORICAL TRUST

MHT No. <u>CH-386</u>

SHA Bridge No. CH 34 Bridge name Trinity Church Road over Gilbert Swamp Run
(Dyson Bridge)
LOCATION:
Street/Road name and number [facility carried] Trinity Church Road
City/town Dentsville Vicinity X
County Charles
This bridge projects over: Road Railway Water X Land
Ownership: State County X Municipal Other
HISTORIC STATUS:
In the heider to and I take the second
National Register-listed district National Register-determined-eligible district
Locally-designated district Other
Name of district
BRIDGE TYPE:
Timber Bridge:
Beam Bridge Truss -Covered Trestle Timber-And-Concrete
Stone Arch Bridge
Metal Truss Bridge
Movable Bridge:
C
Vertical Lift Bascule Single Leaf Bascule Multiple Leaf Retractile Pontoon
Metal Girder:
Rolled Girder Rolled Girder Concrete Engaged
Plate Girder Plate Girder Concrete Encased
Metal Suspension
Metal Arch
Metal Cantilever
Concrete X:
Concrete Arch Concrete Slab X Concrete Ream Rigid Frame
Other Type Name Kigid Flame

CH-386

<b>DESCRIPTION:</b>				
Setting: Urban	Small town	Rural	Y	
Describe Setting:				-
Bridge No. CH 34 carries	Trinity Church Road over Gillest, while Gilbert Swamp Road	ert Swamp Run ir	Charles County	Trinita
	est, while Ollbert Swamp Kiln	flows north to sou	th. The land are	. IIIIIIty
bridge is in active use as	farmland.		· · · · · · · · · · · · · · · · · · ·	ruliu tile
width of 27' from curb to railings, is in good condition 1993. The concrete slab dispersion were replaced with a timb rebuilt again in 1991. T	and Substructure: Filbert Swamp Run is a two spans of 1958. The span lengths are curb. The superstructure, components of the bituminous concrete riseck was rebuilt in 1958 and is the bridge is posted at 30,000 for the bridge i	onsisting of the sliding surface was rein good condition	37' and a clear rab, the roadway approach between 1'. The concrete p	roadway and the 991 and parapets
combination units.		•	, , ,	
at the wingwall/abutment c	of the abutments, wingwalls and shave full-height vertical crack onstruction joints. The concrete have scour at the waterline.	cs at the center of	the abutment ste	ms and
Discuss Major Alterations The concrete slab was reb unknown date.  HISTORY:	erilt in 1958 and the parapets	were replaced wi	th timber railing	s at an
WHEN was the bridge buil	lt: 1927. rebuilt 1958			
This date is: Actual	X Feti	mated		
Source of date: Plaque Other (specify)	Design plans	County bridge file	s/inspection form	1 <u>X</u>
WHY was the bridge built? Maryland's primary and se volume of cars in use after	condary roads had become in	adequate to the l	nuge freight trucl	ks and
WHO was the designer? Unknown				
WHO was the builder? Unknown				
WHY was the bridge altered. To extend the life of the br	d? idge			
WAS this bridge built as pa Yes, post World War I imp	art of an organized bridge-bui rovements to primary and sec	lding campaign? ondary roads.		

#### **SURVEYOR/HISTORIAN ANALYSIS:**

This b	bridge may have National A - Events	Register significance B- Person	for its association with:
	C- Engineering/architect	tural character	

This bridge does not have National Register significance.

## Was the bridge constructed in response to significant events in Maryland or local history?

Reinforced concrete slab bridges are a twentieth century structure type, easily adapted to the need for expedient engineering solutions. Reinforced concrete technology developed rapidly in the early twentieth century with early recognition of the potential for standardized design. The first U.S. attempt to standardize concrete design specifications came in 1903-1904 with the formation of the Joint Committee on Concrete and Reinforced Concrete of the American Society of Civil Engineers.

Maryland's roads and bridge improvement programs mirrored economic cycles. The first road improvement of the State Roads Commission was a 7 year program, starting with the Commissions establishment in 1908 and ending in 1915. Due to World War I, the period from 1916-1920 was one of relative inactivity; only roads of first priority were built. Truck traffic resulting from war related factories and military installations generated new, heavy traffic unanticipated by the builders of the early road system. From 1920-1929, numerous highway improvements occurred in response to the increase in Maryland motor vehicles from 103,000 in 1920 to 320,000 in 1929, with emphasis on the secondary system of feeder roads which moved traffic from the primary roads built before World War I. After World War I, Maryland's bridge system also was appraised as too narrow and structurally inadequate for the increasing traffic, with plans for an expanded bridge program to be handled by the Bridge Division, set up in 1920. In 1920 under Chapter 508 of the Acts of 1920 the State issued a bond of \$3,000,000.00 for road construction; the primary purpose of these monies was to meet the state obligations involving the construction of rural post roads. The secondary purpose of these monies was to fund (with an equal sum from the counties) the building of lateral roads. the number of hard surfaced roads on the state system grew from 2000 in 1920 to 3200 in 1930. By 1930, Maryland's primary system had been inadequate to the huge freight trucks and volume of passenger cars in use. Most improvements to local roads waited until the years after World War II.

# When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area?

Although built following the post World War I construction phase, this bridge did not greatly effect the area surrounding it. The structure did not increase settlement or industry.

# Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from the historic/visual character of the potential district?

No, this bridge is not located in an area which is eligible for historic designation.

#### Is the bridge a significant example of its type?

No, this structure is not a significant example of its type. Its character defining elements are not in their original state.


### Does the bridge retain integrity of important elements described in Context Addendum?

No, this structure does not retain the integrity of its original design because of its character defining elements have been replaced.

Is the bridge a significant example of the work of a manufacturer, designer, and/or engineer? No, this structure is not a significant example of the manufacturer.

Should the bridge be given further study before an evaluation of its significance is made? No, this structure should not be given further study. Although it reflects the state's post

construction needs of expanding the secondary road systematic integrity in doubt.	stem, its current condition has placed its
BIBLIOGRAPHY:	
County inspection/bridge files X S Other (list):	SHA inspection/bridge files X
SURVEYOR:	
Date bridge recorded 8/11/95 Name of surveyor Timothy J. Tamburrino	
Organization/Address P.A.C. Spero & Company, 40 W. Omaryland 21204	Chesapeake Avenue, Suite 412, Baltimore,
Dhoma march - 410 200 400 5	number 410-296-1670





105 5 CH386 BRIDGE # CH 34 CHARLES COUNTY D. BHAUMIK 2-2-95 MARYLAND SHPOSHA TRINITY CHURCH ROAD OVER GILBERT SWAMP RUN LOOKING WORTH ON TRINITY ROAD



2 OF 5 CH386 BRIDGE # CH 34 CHARLES COUNTY DI BHAUMIK 2-2-95 MARYLAND SHA TRINITY CHURCH ROOD OVER GILBERT SWAMP RUN LOOKING SOUTH ON TRINITY CHURCH ROAD



CH 386 BRIDGE # CH 34 CHARLES COUNTY D. BHOCMIK 2-2-95 MARYLAND SHPOSHA TRINITY CHARCH ROAD OVER GILBERT SWAMP RUN LOOKING EAST (DOWNSTREAM FACE)



4 OF 5 CH386 BRIDGE # CH34 CHARLES COUNTY D. BHOUMIK 2-2-95 MARYLAND SHOOSHA TRINITY CHURCH ROAD OVER CILBERT SWAMP RUN LOOKING EAST (DOWNSTRENDY FACE)



5 OF 5 CH386 BRIDGE # CH34 CHARLES COUNTY D. BHAUMIK 2-2-95 MARYLAND SHPO SHA TRINITY CHURCH ROAD OVER GILBERT EWAMP RUN LOOKING WEST ( UPSTREAM FACE)